

SOLIDWORKS KEYBOARD SHORTCUTS

SELECTION FILTERS

V - Filter Vertices
X - Filter Faces
E - Filter Edges
Y - Accept Edge
F8 - Hide/Show Pane
F5 - Toggle Filter Toolbar
F6 - Toggle Select Filter

SEARCH TOOLS

H - SolidWorks Help
K - Knowledge Base
O - Community Forum
W - Commands
I - Files & Models

EDIT COMMANDS

CTRL+SHIFT+C - Copy Appearance
CTRL+SHIFT+V - Paste Appearance
CTRL+B - Rebuild
DELETE - Delete
F7 - Spell Checker

MISCELLANEOUS

C - Expand/Collapse Tree
SHIFT+C - Collapse All
CTRL+T - Show Flat Tree
CTRL+Q - Force Regen
HOME - FM Tree Top
END - FM Tree Bottom

GLOBAL COMMANDS

CTRL+Z - Undo
CTRL+Y - Redo
ENTER - Repeat Last
CTRL+A - Select All
CTRL+C - Copy
CTRL+X - Cut
CTRL+F - Find/Replace
CTRL+V - Paste
CTRL+N - File New
CTRL+O - File Open
CTRL+S - File Save
CTRL+W - File Close
CTRL+P - Print
R - Browse Recent Docs

VIEW MANIPULATION

F - Zoom to Fit
Z - Zoom Out
G - Magnifying Glass
SHIFT+Z - Zoom In
F11 - Full Screen
CTRL+SHIFT+Z - Previous
CTRL+R - Redraw
SPACEBAR - Orientation
F9 - Feature Manager Tree
F10 - Toolbars
CTRL+F1 - Task Pane
CTRL+SPACEBAR - Select

WINDOWS KEY +

E - Open file explorer
R - Run command
P - Manage monitors

